

**General**

Latitude: 39-12-35.2000N      Elevation: 691  
Longitude: 93-55-40.8000W      City: LEXINGTON

**Runways**

04/22: 40 ft x 2925 ft (ASPH)      13/31: 125 ft x 3100 ft (TURF)  
Lighting: NSTD      Lighting: --  
VGSI: Right Traffic: N/N      VGSI: Right Traffic: N/N

18/36: 125 ft x 2250 ft (TURF)  
Lighting: --  
VGSI: Right Traffic: N/N

**Communications**

Unicom: 122.7      Approach: 135.575  
CTAF: 122.7      Lights: 122.7

**Contacts**

Manager: TOM DOLPHIN  
42938 W. 64TH STREET  
HENRIETTA, MO 64036  
Phone: 816-290-5415      Email:

**Services**

Attendance: M: ALL      D: SAT-SUN      H: 0800-DUSK  
M: ALL      D: MON-FRI      H: 0900-DUSK

Fuel: 100LL  
Repairs: Airframe: Power Plant:  
Storage: Yes  
Overnight Hangar: No  
Ground Transportation: Car Rental from Nearby City: Y, Courtesy Car: Y  
Vending Machines: Y

**Remarks**

SPORT AVIATION ACTIVITIES IN PROGRESS ON WEEKENDS. BIRDS INVOF ARPT DURING SPRING RAINS & FLOODING. TREES IN RY VISIBILITY ZONE BETWEEN RY 22 END AND RY 13 END. NTSD RY SAFETY AREA BYD RY 22, 13, 18, & 31 ENDS; INCORRECT TERRAIN GRADES, INSUF LENGTH, DITCH, BRUSH, TREES, POLE, CROPS. RY 22 +1-50 FT TALL TREES AND BRUSH FIRST 1,000 FT OF RY 22, 86-250 FT NORTH OF RY PAVEMENT EDGE & 100-250 FT SOUTH OF RY PAVEMENT EDGE. 100LL UNAVBL INDEFY. THIS AIRPORT HAS BEEN SURVEYED BY THE NATIONAL GEODETIC SURVEY.

**FBOs**

MO RIVER VALLEY SKYDIVER (816) 290-5415

**Notes:**

Be alert to parachute operations on and in vicinity of airport. Activate lgtg-CTAF. Use caution-deteriorating runway conditions exist.